

G&G ROCK Y FLATS

&G ROCKY FLATS INC

WICKY FLATS PLANT P O BOX 464 GOLDEN COLORADO 80402-0464 (303) 966 7000



000030483

June 9 1993

93 RF 5535

R J Schassburger
Deputy Director
Environmental Restoration Division
DOE RFO

STANDARD OPERATING PROCEDURE FO 23 RLB 223 93

Attached is a draft letter for submittal to the Colorado Department of Health (CDH). Based on discussions during finalization of Standard Operating Procedure FO 23, the CDH requested an update on management of IDM generated at Operable Unit 1 (OU1) and Operable Unit 2 (OU2).

Existing data was evaluated for any detectable organics and for results above the upper tolerance level for metals. These exceedances were then correlated to the corresponding drums to determine whether RCRA management is required. Based on these criteria the results were as follows:

220 drums not currently managed from AAC s have exceedences

586 drums at OU1 and OU2 drill sites have no exceedences

155 drums in RCRA Unit 18 03 have no exceedences

247 OU1 and OU2 drums still do not have results associated with the IDM

The 220 drums currently in AAC's will be moved to interim storage. The 155 drums in RCRA Unit 18 03 with no exceedences will be disposed of at the RFP landfill and the 586 drums with no exceedences currently at the well sites will either be dumped at the site or disposed of at the landfill.

CLASSIFICATION

CN 621		
UNCLASSIFIED		
CONFIDENTIAL		
SECRET		

AUTHORIZED CLASSIFIER

SIGNATURE _____

6/7/85 UUU
DAT-

N REPLY TO RFP CC NO

ACTION	ITEM	STATUS
1	2	3
4	5	6
7	8	9
10	11	12
13	14	15
16	17	18
19	20	21
22	23	24
25	26	27
28	29	30
31	32	33
34	35	36
37	38	39
40	41	42
43	44	45
46	47	48
49	50	51
52	53	54
55	56	57
58	59	60
61	62	63
64	65	66
67	68	69
70	71	72
73	74	75
76	77	78
79	80	81
82	83	84
85	86	87
88	89	90
91	92	93
94	95	96
97	98	99
100	101	102
103	104	105
106	107	108
109	110	111
112	113	114
115	116	117
118	119	120
121	122	123
124	125	126
127	128	129
130	131	132
133	134	135
136	137	138
139	140	141
142	143	144
145	146	147
148	149	150
151	152	153
154	155	156
157	158	159
160	161	162
163	164	165
166	167	168
169	170	171
172	173	174
175	176	177
178	179	180
181	182	183
184	185	186
187	188	189
190	191	192
193	194	195
196	197	198
199	200	201
202	203	204
205	206	207
208	209	210
211	212	213
214	215	216
217	218	219
220	221	222
223	224	225
226	227	228
229	230	231
232	233	234
235	236	237
238	239	240
241	242	243
244	245	246
247	248	249
250	251	252
253	254	255
256	257	258
259	260	261
262	263	264
265	266	267
268	269	270
271	272	273
274	275	276
277	278	279
280	281	282
283	284	285
286	287	288
289	290	291
292	293	294
295	296	297
298	299	300
301	302	303
304	305	306
307	308	309
310	311	312
313	314	315
316	317	318
319	320	321
322	323	324
325	326	327
328	329	330
331	332	333
334	335	336
337	338	339
340	341	342
343	344	345
346	347	348
349	350	351
352	353	354
355	356	357
358	359	360
361	362	363
364	365	366
367		

OPEN CLOSURE

3 • RTI

APPROVALS

MCB TWA
FIG & TYPE INITIALS

F 6469 R 3-3'


ADMIN RECORD

^ DU(1) 11(12)

 $\frac{1}{3}$

R J Schassburger
June 9 1993
93 RF 5535
Page 2

A round table discussion of FO 23 was held on Friday June 4 Outstanding issues including drum labeling were discussed If additional information is required please contact Marla Broussard of my staff at extension 8517



R L Benedetti
Associate General Manager
Environmental Restoration
EG&G Rocky Flats Inc

MCB la

Orig and 1 cc R J Schassburger

Attachment
As Stated

DRAFT

Colorado Department of Health
Hazardous Materials and Waste Management Division

SUBJECT MANAGEMENT OF INVESTIGATIVE DRILLING DRUMS HAS BEEN REEVALUATED

The reevaluation of investigative derived material (IDM) generated from the Operable Unit 1 (OU1 and Operable Unit (OU2) projects has been completed. Based on detectable levels (MDL) for organics and detections above upper tolerance levels for metals, 155 of the 282 drums moved from Individual Hazardous Substance Sites (IHSSs) and Potential Areas of Concern (PACs) to RCRA Unit 18 03 contain no exceedances. It is planned that the contents IDM of these 155 drums will be disposed of at the Rocky Flats landfill. The empty drums and rigid liners will be repainted, restenciled, renumbered, and reused if possible. Drums and liners that are not in reusable condition will be cut up and sent off site for recycling.

Initial characterization of analytical results for the OU1 and OU2 drilling projects also show 220 drums of IDM with exceedances are presently located at well sites. These drums will be moved to a RCRA Unit. The 220 drums are not from IHSSs or PACs but are from the recently identified additional areas of concern (AACs). An additional 247 drums of IDM are located in AACs and are without chemical analysis to date.

Five hundred and eighty six additional drums of IDM located at drill sites have no exceedances. These drums will be either dumped at the drill sites or emptied at the landfill.

If you need additional information, please contact Rich Schassburger at 933 4888.

Department of Energy

DRAFT